

TM2B, ION Fit, & TM4

Please follow the steps below to install your Touch Monitor POS-X TM2B/ ION Fit/TM4 system.

1

Unpackaging

1. Remove the foam packing with your POS-X touch monitor from the box and set it on a sturdy surface
2. Remove the foam pads from each side
3. Remove the protective plastic covering from the touch monitor

TM2B



2

Connect the Power


1. Locate the accessory pack
2. Remove the power cable from the accessory pack
3. Connect the power cable to the power supply
[For the ION Fit connect the power supply to the monitor]
4. Connect the power cable to the wall outlet

ION Fit



Locate the power supply in the box and connect it to the terminal

TM4



Drivers

For all driver downloads, please visit:
www.pos-x.com/downloads

3

Connect the Cables

1. Connect one end of the VGA cable to the computer and the other end to the monitor.
2. Connect the squared end of the USB cable to the monitor, and the rectangular end to the computer.
3. Connect any peripherals. Please see peripheral installation instructions



4

Power On ION Fit

ION Fit Power button is located on the right side of the base behind the screen.

TM4

TM4 Power button is located on the under side of the screen.

TM2B

TM2B Power button is located on the bottom of the screen.



ION Fit Cable Management



Run all cables through the cable clip on the base of the ION Fit, along the bottom of the unit, and out the back for optimal cable management.